

25X1




25 YEAR RE-REVIEW

25X1

Information





- A. A 6 mm glass overlap (inside and out) showed a bright reddish surface through glass which appeared to be 0.5 mm on both sides
- B. A 2 mm high glass ridge appeared yellowish
- C. Copper ferrul was fined off on both sides to an edge. All welding had been done by a Russian woman glass H.F. welding operator in  $2\frac{1}{2}$  to 3 minutes

25X1

TOP SECRET

SECURITY INFORMATION

25X1

